ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone
YELAHANKA

Ward No.
3

Ward Name
Alturu

Street ID
W0248

Street Name
NA

Significant Landmark
2nd main road Yelahanka 5th Phase

Segment No.
3/S-W0248/S092023

Total Length (m)
125.70

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	125.70	77.572947	13.105343	77.571789	13.105369	W0373	W0357

Work Details

History of Road / Lane / Circles

Name of the Work
Providing of cobble stone footpath in ward no 03 Yelahanka Satellite Town Sub division Yelahanka zone

Sanctioned Estimated Amount (Rs.)
5000000

Sanctioned Year
2017

Year
2017 - 2018

Type of Work
Footpath Layering

Other Work Type

Tender
Not a Tender

Work Details
Providing of cobble stone footpath in ward no 03 Yelahanka Satellite Town Sub division Yelahanka zone

Job No. / Work Code
003-17-000035

Work Order No.
BBMP/EE (YNK.D)/WO/70/2017-18

Work Order Date
16/06/2017

Period of Extention
90 DAYS

Defect Liability Period From
30/06/2017

Defect Liability Period To
29/06/2018

Multiple road involved with the same Job No/ Work Code #
Yes

Contractor Details

Name of Contractor
KRIDL

Contractor Reg No (BBMP/PWD)

Expenditure Booked \ Released (Rs)
4999847.69

Phone No.
9449863065

E-Mail ID

Field Inspection Details

Zone: YELAHANKA **Ward No:** 3 **Ward Name:** Alturu

Date: 18/07/2017 **Time:** 21:52:19 RH20170718215219 **Street ID:** W0248

AE-03

		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	18/07/2017	17/08/2017	COMPLETED
SE	VASU K M	18/07/2017	17/08/2017	COMPLETED
EE	VASU K M	18/07/2017	17/08/2017	COMPLETED
AEE	ASHOK	18/07/2017	17/08/2017	COMPLETED
AE	CHANDRAKANTH	18/07/2017	17/08/2017	COMPLETED
AE	CHANDRAKANTH	18/07/2017	17/08/2017	COMPLETED

Zone: YELAHANKA Ward No: 3 Ward Name: Atturu Street ID: W0248

Date: 18/07/2017 Time: 21:52:19 RH20170718215219

AE-03

Any Other Information	Name
Date of Inspection	CHANDRAKANTH
18/07/2017	Remarks
	COMPLETED

Category	Image	Photo Remark
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.
Footpath Condition		This photo seems out of range.

Zone: YELAHANKA Ward No: 3 Ward Name: Atturu Street ID: W0248

Date: 18/07/2017 Time: 21:52:19 RH20170718215219

AE-03